

TAMPA BAY PILOTS ASSOCIATION  
GUIDELINE OR HANDLING RECOMMENDATION CHANGE

DATE OF EFFECTIVE CHANGE 8/16/12 SURVEY DATE APRIL 2012

BERTH NAME OF CHANGE PORT MANATEE # 4 & # 5

NATURE OF CHANGE: DRAFT  LENGTH/BEAM \_\_\_\_\_

TIDAL \_\_\_\_\_ TUG REQ. \_\_\_\_\_

DESCRIPTION OF CHANGE:

REDUCE MAXIMUM DRAFT Δ/S TO 38'00" + TIDE

NOTIFICATION OF INTERESTED PARTIES: FACILITY  AGENTS  PILOTS  USCG

TAMPA BAY PILOTS ASSOCIATION  
GUIDELINE OR HANDLING RECOMMENDATION CHANGE

DATE OF EFFECTIVE CHANGE 8/16/12 SURVEY DATE APRIL 2012

BERTH NAME OF CHANGE PORT MANATEE # 12

NATURE OF CHANGE: DRAFT  LENGTH/BEAM \_\_\_\_\_

TIDAL \_\_\_\_\_ TUG REQ. \_\_\_\_\_

DESCRIPTION OF CHANGE:

REDUCE MAX DRAFT Δ/S TO 39'06" + TIDE FOR  
NORTHERN 900' OF BERTH. SOUTH OF 900' MARK, MAX  
DRAFT OF 25'

NOTIFICATION OF INTERESTED PARTIES: FACILITY \_\_\_\_\_ AGENTS \_\_\_\_\_ PILOTS \_\_\_\_\_ USCG \_\_\_\_\_